



JUPITER, FLORIDA



Anode connection terminates within junction box along with output potential monitoring facility.



Completed Retrofit installation.
Fast, light weight, and esthetically pleasing to the eye.



Anode wrap with zinc lined inner face clearly visible being positioned around pile.



Induced tensioning of wrap underway. Residual elasticity within wrap fabric locks the system in place throughout design life. Zinc anode connection bar visible on left face of pile,

Corrosion Control International (Division of Slickbar Products Corp)
18 Beach Street, Seymour, CT 06483 U.S.A.
Ph: 203-888-7662 • Fax: 203-888-7720 • info@slickbar.com • www.slickbar.com